

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5





FIG. 6

FIG. 7





FIG. 8

209020" 6999900F

FIG. 10A

PEN OPERATION MODE		OUTPUT COORDINATE MODE	PEN TIP SW 41	SW1 42_a	SW2 42_b	DRIVING MODE		COORDINATE CALCULATION VALUE IN Z-AXIS DIRECTION
						1(50p/sec)	2(40p/sec)	
PEN INPUT OPERATION	PEN DOWN	ABSOLUTE COORDINATES	ON	—	—	○		(300mm OR LESS)
	PEN UP	ABSOLUTE COORDINATES	OFF	ON	OFF		○	300mm OR LESS
PROXIMITY INPUT OPERATION	PEN UP	ABSOLUTE COORDINATES	OFF	OFF	ON		○	300mm OR LESS
	PEN DOWN	ABSOLUTE COORDINATES	OFF	ON	ON	○		300mm OR LESS
REMOTE INPUT OPERATION	PEN UP	RELATIVE COORDINATES	OFF	ON	OFF		○	1000mm OR MORE
	PEN UP	RELATIVE COORDINATES	OFF	OFF	ON		○	1000mm OR MORE
	PEN DOWN	RELATIVE COORDINATES	OFF	ON	ON	○		1000mm OR MORE

FIG. 10B





FIG. 11

FIG. 12




FIG. 13

